GujRAMS - Data Services #1850

SH068 (Pilot Road) - Reuploading

21/03/2025 05:23 PM - Madhuri Pinky Mendu

Status:	New		**Start date:**	19/03/2025
Priority:	Normal		**Due date:**	
Assignee:	Madhuri Pinky Mendu		**% Done:**	0%
Category:			**Estimated time:**	0:00 hour
Target version:			**Spent time:**	0:00 hour
Deployed In:	Demo Environment		**Category:**	

Description

On 19Mar2025,Verified given data, Deleted previous SH068 data of 2025year in geodemo. While creating new links, a issue is found(Linkcode is generating by adding only last 4digits of StartChainage,but actually it should generate by adding full Value of StartChainage.)Informed to developers.I have modified the linkcodes from backend,which were created only by using 4digits.
On20Mar2025,Imported GPS data and Some tables data of RIS Module. Some are having errors. Informed to Varun sir.
On21Mar2025,Imported given few corrected data for error thrown tables only. Again informed about few table errors to varun sir.

Files

RIS_DataTemplate SH-68 updated (21-03-2025) (00000002).xlsx	1.55 MB	21/03/2025	Madhuri Pinky Mendu
RIS_DataTemplate SH-68 updated (17-03-2025).xlsx	2.17 MB	21/03/2025	Madhuri Pinky Mendu