

Rwanda RAMS - Task #1414

Data Verification - 07-10-2024

15/10/2024 03:02 PM - Krishna Kanth A

Status:	New	Start date:	15/10/2024
Priority:	Normal	Due date:	
Assignee:	Durga Konduru	% Done:	0%
Category:		Estimated time:	0:00 hour
Target version:		Spent time:	0:00 hour
Deployed In:		Category:	
Description			
Need to verify the Road Furniture data as per ArcGIS Imagery Base Map e.g. bridge on NR6 (also we need to check internally using video data and road furniture chainages e.g. NR6 - 106801 and 101052 - check road furniture check with videos).			

History

#1 - 15/10/2024 03:11 PM - Krishna Kanth A

- Tracker changed from Bug to Task